

July 19, 1945

NOTICE OF CHANGE ON GREENLEE'S NO. 770 & 775 BENDER
EQUIPMENT ON PINS AND CONNECTING BARS

We have made changes on the No. 770 & 775 Bender Cross Bars, and Connecting Bars on the No. 775, 770-T, and 770-R. This change permits quickly shifting the Support Castings on 770 and 775, and the roller on 770-T and 770-R.

On assembling No. 770 and 775 Benders, attach the Connecting Bars first. The lower Cross Bar with the lug or feet goes on the floor underneath the lower Connecting Bars.

No. 770 Benders with serial numbers 61635 and smaller, use the following:

2	-	Required	AA-541	Support Casting Pins
1	-	"	AA-467	Upper Cross Bar
1	-	"	AA-467	Lower Cross Bar

No. 770 Benders with serial numbers 61636 and up

2	-	Required	AA-1272	Support Casting Pins (new)
1	-	"	AA-467	Upper Cross Bar (as before)
1	-	"	AA-1274	Lower Cross Bar (new)
4	-	"	AA-466	Connecting Bars (as before)

No. 770-T or 770-R Benders with serial numbers 61635 and smaller

1	-	Required	AA-973	Upper Connecting Bar
1	-	"	AA-973	Lower Connecting Bar
1	-	"	AA-938	Roller Pin

No. 770-T or 770-R Benders with serial numbers 61636 and up

1	-	Required	AA-973	Upper Connecting Bar (as before)
1	-	"	AA-1162	Lower Connecting Bar (new)
1	-	"	AA-1273	Roller Pin

Greenlee No. 775 Benders with serial numbers 8347 and lower

2	-	Required	AA-590	Cross Bars
4	-	"	AA-591	Connecting Bars

Greenlee No. 775 Benders with serial numbers 8348 to 8547

2	-	Required	AA-1242	Cross Bars
4	-	"	AA-1243	Connecting Bars

Greenlee No. 775 Benders with serial numbers 8548 and up

2	-	Required	AA-1269	Support Casting Pins
1	-	"	AA-1242	Upper Cross Bar
1	-	"	AA-1275	Lower Cross Bar
4	-	"	AA-1243	Connecting Bars

GREENLEE TOOL COMPANY

A. H. HAWKINSON